WATER TEST REAGENT

For Laboratory Use Only

SMALL VOLUMES USED CONTAINER SIZE RANGE

MATERIAL SAFETY DATA SHEET

| • | OUNCE. | • | CALLON | MAXIMUM |
|---|---------|----|--------|-----------|
| 2 | UUMUE • | ٠. | | May (Moth |

| Section | 1 | - PRODUCT | IDENTIFICATION |
|---------|---|-----------|----------------|
| | | | |

MANUFACTURER'S NAME DEARBORN CHEMICAL CO., Subsidiary, W. R. Grace & Co. EMERGENCY PHONE NO. 312/438-8241

300 Genesee St., Lake Zurich, IL 60047

CHEMICAL NAME AND SYNONYMS Xylenol orange indicator TRADE NAME OR CODE IDENT.

Code 562

Section 2 - INGREDIENTS

CAS No.

EXPOSURE CRITERIA

NON - HAZARDOUS MATERIAL

The product identified in this Data Sheet Is NOT a hazardous material within the meaning of Title 29, Code of Federal Regulations 1915, 1916, 1917.

| Section 3 – PHYSICAL DATA | | | | <u> </u> | | , |
|---|--------------|--|-------------------|----------------|----------------|----------|
| BOILING POINT, 760mm Hg | NIA | MELTING POINT | | | NA | |
| SPECIFIC GRAVITY (H20 = 1) | //,, | VAPOR PRESSURE | | | 4 | |
| APOR DENSITY (AIR = 1) | Le | SOLUBILITY IN H 2O, % BY WT. | | | appreciable | |
| % VOLATILES BY VOLUME | t.{ | EVAPORATION RATE,= 1 | | | NA | |
| APPEARANCE AND ODOR Purpl | r | рН | | | 11/12 | |
| Section 4 – FIRE AND EXPLOSE | SION HA | ZARD DATA | | | | / |
| FLASH POINT (and Method Used) None | | E LIMITS in AIR, % by VOLUME AUTO IGNITION | | | ON TEMPERATURE | |
| EXTINGUISHING MEDIA | . 0 | Foam | □ CO ₂ | ☐ Dry Chemical | Oth | er |
| SPECIAL FIRE FIGHTING PROCEDUR | ES | | | | | |
| | | non | Q | | | |
| UNUSUAL FIRE AND EXPLOSION HA | ZARD | | nono | | | · |
| Section 5 – REACTIVITY DAT | A | | | | | |
| STABILITY (Normal Conditions) | ONS TO AVOID | | | • | | |
| 🐒 Stable 🔲 Unstable | | | rone | | | |
| INCOMPATIBILITY (Materials to Avoid) | | none | | | : • | |
| HAZARDOUS DECOMPOSITION PROD | OUCTS | No | ne | | | • |
| HAZARDOUS POLYMERIZATION May Occur Will Not Occur | CONDI | TIONS TO AVO | DID y | Lone | | |
| | | | | | (ov | er) |

| Section 6 - HEALTH HAZARD INFO | RMATION | |
|---------------------------------------|-------------------------|--|
| EXPOSURE LIMIT Not established | | |
| | • | |
| EFFECTS OF OVEREXPOSURE | - | |
| INHALATION | Not expected | |
| · | | |
| | | |
| | • | |
| INGESTION No. 1 - 1 - 1 - 1 | 5 | TE described dutable large groups of |
| water. If discomfort occurs, | | If ingested, drink large amount of |
| | | |
| | | |
| | | |
| SKIN OR EYE CONTACT | ouder from skin o | r eyes and flush with clear water. |
| - | • | Wash skin with soap and warm water. |
| prince adacogs soras | | |
| | | |
| | | |
| EMERGENCY AND FIRST AID PROCEDURES | see a | 1. 4 |
| | pele u | voere- |
| | ٠. | |
| | | |
| | MICODIAL TION | |
| Section 7 – SPECIAL PROTECTION | INFORMATION | |
| VENTILATION REQUIREMENTS | Thekan | real (|
| · | <i>,</i> , | <u> </u> |
| RESPIRATORY PROTECTION (Specify Type) | | _ |
| • | pron- | |
| EYE PROTECTION | GLO\ | /ES (Specify Type) |
| Safety glasses | | none |
| OTHER PROTECTIVE CLOTHING AND EQUI | PMENT (Specify Type) | |
| OTHER PROTECTIVE CLOTHING AND EGO! | FIME IAT (Specify Type) | |
| • | | hone |
| Section 8 SPILL OR LEAK PROCE | DUBES | |
| STEPS TO BE TAKEN IF MATERIAL IS BELE | | |
| Place spilled material in was | | rash disposal. |
| • | | |
| WASTE DISPOSAL METHOD Dispose | small amounts to d | rain using large amount of water to dilute the in container for authorized |
| chemical scavenger service. | practing capped bot | tie in container for authorized |
| Section 9 - SPECIAL PRECAUTIONS | S | |
| PRECAUTIONS TO BE TAKEN IN HANDLING | | |
| Protect container from physic. | | losed when not in use. |
| | | · · · · · · · · · · · · · · · · · · · |
| OTHER PRECAUTIONS | | |
| Chomiania NOT | Water Tectine De | eagent - NOT RESTRICTED |
| Shipping (vane. DO) | , water resting Re | agent - NOI MESIKICIED |
| IATA | | Prepared By W. M. Morris |
| | | |
| | | Date: 8/79 |